



BA07-560 S-2, M-2





BA07-560 LA-2, LB-2



Типоразмер	l_{10}	l_{30}	l_{34}	d_{30}	b_{31}	b_{33}	h_{31}	Масса, кг
BA07A,M-560S-2	630	2090 ^{+15,0}	1320	954 ^{+9,0}	741 ^{+8,0}	685	1076 ^{+9,0}	3150
BA07A,M-560M-2	710	2130 ^{+15,0}	1350					3400
BA07A,M-560LA-2	800	2180 ^{+15,0}	1400	1064 ^{+9,0}	800 ^{+8,0}	745	1130 ^{+9,0}	4870
BA07A,M-560LB-2	900	2270 ^{+15,0}	1490					5250

BA07-630 S; M; L; LA

BA07-630 Mk; Lk



Типоразмер	Напряжение, В	l_{10}	l_{30}	l_{34}	d_1	d_{30}	b_{31}	b_{33}	h_{31}	h_{34}	Масса, кг	
BA07A,M-630S-4	6000	1000	2245 ^{+17,5}	1252	140	1448 ^{+16,0}	980 ^{+9,0}	953	1490 ^{+12,5}	585	6600	
	10000						1150 ^{+10,5}	1164		538	6650	
BA07A,M-630M-4	6000	1120	2375 ^{+17,5}	1382		1448 ^{+16,0}	980 ^{+9,0}	953		1490 ^{+12,5}	585	7200
	10000						1150 ^{+10,5}	1164			538	7250
BA07A,M-630Mk-4	6000	1400	2445 ^{+17,5}	1252		1440 ^{+16,0}	980 ^{+9,0}	953		1530 ^{+12,5}	585	8000
	10000						1150 ^{+10,5}	1164			538	8050
BA07A,M-630L-4	6000	1250	2585 ^{+21,0}	1592		1528 ^{+16,0}	1020 ^{+10,5}	993	1530 ^{+12,5}		605	8800
	10000						1190 ^{+10,5}	1200			555	8850
BA07A,M-630LA-4	6000	1600	2855 ^{+21,0}	1890		1528 ^{+16,0}	1020 ^{+10,5}	993	1530 ^{+12,5}		605	11000
	10000						1190 ^{+10,5}	1200			555	11050
BA07A,M-630Lk-4	6000	1600	2855 ^{+21,0}	1592		145	1520 ^{+16,0}	1020 ^{+10,5}	993	1490 ^{+12,5}	605	11000
	10000							1190 ^{+10,5}	1200		555	11050
BA07A,M-630S-6	6000	1120	2375 ^{+17,5}	1370	140	1448 ^{+16,0}	980 ^{+9,0}	953	1490 ^{+12,5}		585	7200
	10000						1150 ^{+10,5}	1164			538	7250
BA07A,M-630M-6	6000	1250	2585 ^{+21,0}	1590		1448 ^{+16,0}	980 ^{+9,0}	993	1530 ^{+12,5}		605	8200
	10000						1150 ^{+10,5}	1200			555	8250
BA07A,M-630S-8	6000	1120	2375 ^{+17,5}	1370		1448 ^{+16,0}	980 ^{+9,0}	953	1490 ^{+12,5}	585	7000	
	10000						1150 ^{+10,5}	1164		538	7050	
BA07A,M-630M-8	6000	1250	2585 ^{+21,0}	1590		1448 ^{+16,0}	980 ^{+9,0}	993	1530 ^{+12,5}	605	8000	
	10000						1150 ^{+10,5}	1200		555	8050	